ARCHITECTURAL STRUCTURES I:
STATICS AND STRENGTH OF MATERIALS

ENDS 231

DR. ANNE NICHOLS

SPRING 2008

lecture
sixteen



elasticity & strain

Deformations

- materials deform
- axially loaded materials change length
- normal stress is load per unit area
- STRAIN:
  - change in length over length
  - UNITLESS



$$\varepsilon = \frac{\delta}{L}$$

Shearing Strain

- deformations with shear
- parallelogram
- change in angles
- stress: τ
- strain: γ
  - unitless (radians)



$$\gamma = \frac{\delta_s}{L} = \tan\phi \cong \phi$$

Shearing Strain

- deformations with torsion
- twist
- change in angle of line
- stress: τ
- strain: γ
  - unitless (radians)

$$\gamma = \frac{\rho\phi}{L}$$



Load and Deformation

- *for stress, need P & A*
- *for strain, need δ & L*
  - *how?*
  - *TEST with load and measure*
  - *plot P/A vs. ε*





Material Behavior

- *every material has its own response*
  - *10,000 psi*
  - *L = 10 in*
  - *Douglas Fir vs. steel?*



Figure 5.20 Stress-strain diagram for various materials.

Behavior Types

- *ductile - "necking"*
- *true stress*

$$f = \frac{P}{A}$$

- *engineering stress*
  - *(simplified)*

$$f = \frac{P}{A_o}$$

Behavior Types

- *brittle*



Fig. 2.11 Stress-strain diagram for a typical brittle material.

- *semi-brittle*



Fig. 2.14 Stress-strain diagram for concrete.

Stress to Strain

- important to us in f-ε diagrams:
  - straight section
  - LINEAR-ELASTIC
  - recovers shape (no permanent deformation)



Figure 5.20 Stress-strain diagram for various materials.

Hooke's Law

- straight line has constant slope
- Hooke's Law

$$f = E \cdot \varepsilon$$



- E
  - Modulus of elasticity
  - Young's modulus
  - units just like stress



Stiffness

- ability to resist strain
- steels
  - same E
  - different <u>yield points</u>
  - different <u>ultimate strength</u>



Figure 5.20 Stress-strain diagram for various materials.

Isotropy & Anisotropy

- ISOTROPIC
  - materials with E <u>same</u> at any direction of loading
  - ex. steel



- ANISOTROPIC
  - materials with <u>different</u> E at any direction of loading
  - ex. wood is <u>orthotropic</u>



Elastic, Plastic, Fatigue

- elastic springs back
- plastic has permanent deformation
- fatigue caused by reversed loading cycles



Fig. 2.18



Fig. 2.20

Plastic Behavior

- ductile



Figure 5.22 Stress-strain diagram for mild steel (A36) with key points highlighted.

Lateral Strain

- or "what happens to the cross section with axial stress"

$$\varepsilon_x = \frac{f_x}{E}$$

$$f_y = f_z = 0$$



- strain in lateral direction
  - negative
  - equal for isometric materials

$$\varepsilon_y = \varepsilon_z$$

Poisson's Ratio

- constant relationship between longitudinal strain and lateral strain

$$\mu = -\frac{lateral\ strain}{axial\ strain} = -\frac{\varepsilon_y}{\varepsilon_x} = -\frac{\varepsilon_z}{\varepsilon_x}$$

$$\varepsilon_y = \varepsilon_z = -\frac{\mu f_x}{E}$$



- sign! $0 < \mu < 0.5$

Calculating Strain

- from Hooke's law

$$f = E \cdot \varepsilon$$

- substitute

$$\frac{P}{A} = E \cdot \frac{\delta}{L}$$

- get $\Rightarrow$

$$\delta = \frac{PL}{AE}$$



Orthotropic Materials

- non-isometric
- directional values of E and μ
- ex:
  - plywood
  - laminates
  - polymer composites





Stress Concentrations

- why we use f_{ave}
- increase in stress at changes in geometry
  - sharp notches
  - holes
  - corners





Figure 5.35 Stress trajectories around a hole.

Maximum Stresses

- if we need to know where max f and f_v happen:



$$\theta = 0° \rightarrow \cos\theta = 1 \qquad f_{\max} = \frac{P}{A_o}$$

$$\theta = 45° \rightarrow \cos\theta = \sin\theta = \sqrt{0.5}$$

$$f_{v-\max} = \frac{P}{2A_o} = \frac{f_{\max}}{2}$$

Maximum Stresses



FIG. 2-37 Shear failure along a 45° plane of a wood block loaded in compression

FIG. 2-38 Slip bands (or Lüders' bands) in a polished steel specimen loaded in tension

Design of Members

- *beyond allowable stress...*
- *materials aren't uniform 100% of the time*
  - *ultimate strength or capacity to failure may be different and some strengths hard to test for*
- *RISK & UNCERTAINTY*



$$f_u = \frac{P_u}{A}$$

Factor of Safety

- *accommodate uncertainty with a safety factor:*

$$allowable\ load = \frac{ultimate\ load}{F.S}$$

- *with linear relation between load and stress:*

$$F.S = \frac{ultimate\ load}{allowable\ load} = \frac{ultimate\ stress}{allowable\ stress}$$

Load and Resistance Factor Design



- *loads on structures are*
  - *not constant*
  - *can be more influential on failure*
  - *happen more or less often*
  - *UNCERTAINTY*

$$R_u = \gamma_D R_D + \gamma_L R_L \leq \phi R_n$$

ϕ - resistance factor

γ - load factor for (D)ead & (L)ive load